

During the two minutes, explore the job site by walking and looking around at the work area (hands-on touch points) and adjacent surroundings. Identify conditions such as:

 Critical indicators (meters) needed for task success.

•

Eliminate hazards,